



Overview: Part of spill impact on 14" Okordia Rumuekpe Pipeine at Edeoha.
 Picture was taken during Joint Investigation on 22nd Dec 2020.



Close-up: 3" nipple installed at 12 o'clock position on 14" Okordia Rumuekpe Pipeine at Edeoha.
 Picture was taken during Joint Investigation on 22nd Dec 2020.