



Overview: Part of spill impact on 36" Nkpoku Ogale Pipeline at Ogale.
Picture was taken during Joint Investigation on 19th Dec 2020.



Close-up: Plugged 5mm Drilled hole at 2 o'clock position on 36" Nkpoku Ogale Pipeline at Ogale.
Picture was taken during Joint Investigation on 19th Dec 2020.