




Overview: Part of spill impact on 36'' Nkpoku Ogale Pipeline at Agbonchia.
Picture was taken during Joint Investigation on 17th Dec 2020.



Close-up 1: 4 nos 5mm drilled hole (leak point 1) at 10 o'clock position on 36inch Nkpoku Ogale Pipeline at Agbonchia. Picture was taken during Joint Investigation on 17th Dec 2020.



Close-up 2: 4 nos 5mm drilled hole at 2 o'clock position on 36inch Nkpoku Ogale Pipeline at Agbonchia. Picture was taken during Joint Investigation on 17th Dec 2020.



Close-up 3: 4 nos 5mm drilled hole (leak point 2) at 1 o'clock position on 36inch Nkpoku Ogale Pipeline at Agbonchia. Picture was taken during Joint Investigation on 17th Dec 2020.



Close-up 4: 4 nos 5mm drilled hole (leak point 3) at 12 o'clock position on 36inch Nkpoku Ogale Pipeline at Agbonchia. Picture was taken during Joint Investigation on 17th Dec 2020.