



**Overview:** Part of spill impact on Obele Flowstation at Obele. Picture was taken during Joint Investigation on 14<sup>th</sup> December 2020.



**Close-up:** Saver pit overflow from drainage on Obele flowstation at Obele. Picture was taken during Joint Investigation on 14<sup>th</sup> December 2020.