



Overview: Overview of incident environment of 12inch Forcados low pressure delivery line at Ogulagha. Picture was taken during Joint Investigation of 14<sup>th</sup> December 2020.



Close-up: External Corrosion at 3 o'clock on 12inch Forcados low pressure delivery line at Ogulagha. Picture was taken during Joint Investigation of 14<sup>th</sup> December 2020