



Overview: Part of spill impact on 14" Okordia - Rumuekpe Pipeline at Ikata. Picture was taken during Joint Investigation of 13th February 2020.



Close-up: Crude oil theft point installed at 12 o'clock position on 14" Okordia - Rumuekpe Pipeline at Ikata. Picture was taken during Joint Investigation of 13th February 2020.