




Overview: Part of spill impact on 28" Bomu - Bonny Pipeline Right of Way at Bodo West. Picture was taken during Joint Investigation of 20th February 2020.



Close-up: 4" Valve installed at 12 o'clock position on 28" Bomu - Bonny Pipeline at Bodo West. Picture was taken during Joint Investigation of 20th February 2020.