



Overview: Part of spill impact on 24" Ogale – Bomu Pipeline Right of Way at Biara . Picture was taken during Joint Investigation of 25th February 2020.



Close-up: 1" valve installed at at 12 o'clock position on 24" Ogale – Bomu Pipeline at Biara . Picture was taken during Joint Investigation of 25th February 2020.