



**Overview:** Part of spill impact on 14" Okordia Rumuekpe Pipeline at Akalamini. Picture was taken during Joint Investigation of 25<sup>th</sup> February 2020.



**Close-up:** Point 1 drilled hole at 12 o'clock position showing water and oil on 14" Okordia Rumuekpe Pipeline at Akalamini. Picture was taken during Joint Investigation of 25<sup>th</sup> February 2020.




Close-up: Point 2 drilled hole at 12 o'clock position on 14" Okordia Rumuekpe Pipeline showing water and oil at Akalamini. Picture was taken during Joint Investigation of 25<sup>th</sup> February 2020.



Close-up: Point 3 drilled hole at 12 o'clock position on 14" Okordia Rumuekpe Pipeline showing water and oil at Akalamini. Picture was taken during Joint Investigation of 25<sup>th</sup> February 2020.



Closeup: Point 4 drilled hole at 12 o'clock position on 14" Okordia Rumuekpe Pipeline at Akalamini. Picture was taken during Joint Investigation of 25<sup>th</sup> February 2020.



Close-up: Point 5 drilled hole at 12 o'clock position on 14" Okordia Rumuekpe Pipeline at Akalamini. Picture was taken during Joint Investigation of 25<sup>th</sup> February 2020.