




Overview: Part of spill impact on 14" Okordia Rumuekpe Pipeline at Akalamini. Picture was taken during Joint Investigation of 27th February 2020.



Close-up: 10mm Drilled hole on 14" Okordia Rumuekpe Pipeline at Akalamini. Picture was taken during Joint Investigation of 27th February 2020.