




Overview: Part of spill impact on 12" ImoRiver 1 – Ogale Pipeline at Umulolo. Picture was taken during Joint Investigation 3rd July 2020.



Close-up: 2inch Bulb valve installed at 12 o'clock position on 12" ImoRiver 1 – Ogale Pipeline at Umulolo. Picture was taken during Joint Investigation 3rd July 2020.