



Overview: Part of spill impact on 18" Assa - Rumuekpe Pipeline at Egbeda. Picture was taken during Joint Investigation 7th July 2020.



Close-up: 2nos Ball valves installed at 12 o'clock position on 18" Assa - Rumuekpe Pipeline at Egbeda. Picture was taken during Joint Investigation 7th July 2020.