




Overview: Part of spill impact on 28" Nkpoku Bomu Pipeline at Rumuewhara . Picture was taken during Joint Investigation 7th July 2020.



Close-up: 5nos 2" Illegal connections installed 12 o'clock position on 28" Nkpoku Bomu Pipeline at Rumuewhara . Picture was taken during Joint Investigation 7th July 2020.



Close-up: 5nos 2'' Illegal connections installed 12 o'clock position on 28'' Nkpoku Bomu Pipeline at Rumuewhara . Picture was taken during Joint Investigation 7th July 2020.