



Overview: Part of spill impact on 18" Assa - Rumuekpe Pipeline at Awara. Picture was taken during Joint Investigation 13th July 2020.



Close-up: 3nos 2" Ball valves installed at 12 o'clock position on 18" Assa - Rumuekpe Pipeline at Awara. Picture was taken during Joint Investigation 13th July 2020.