



Overview: Part of spill impact on 8" Seibou-Ajatiton Bulklineat Agbidiamma. Picture was taken during Joint Investigation 7th July 2020.



Close-up 1: Hack saw cut at 3'o clock position and 9 o'clock position on 8" Seibou-Ajatiton Bulklineat Agbidiamma. Picture was taken during Joint Investigation 7th July 2020.



Closeup 2: Hack saw cut at 3'o clock position and 9 o'clock position on 8" Seibou-Ajatiton Bulklineat Agbidiaama. Picture was taken during Joint Investigation 7th July 2020.



Close-up 3: Hack saw cut at 3'o clock position and 9 o'clock position on 8" Seibou-Ajatiton Bulklineat Agbidiaama. Picture was taken during Joint Investigation 7th July 2020