




Overview: Part of spill impact on 8" Nkali Ogale Pipeline at Odagwa. Picture was taken during Joint Investigation 16th July 2020.



Close-up: 2nos of 1.5inches and 1inch ball valves installed at 12 o'clock position on 8" Nkali Ogale Pipeline at Odagwa. Picture was taken during Joint Investigation 16th July 2020.