



Overview: Part of spill impact on on 12" Oguta Assa Pipeline at Opuoma . Picture was taken during Joint Investigation 15th July 2020.



Close-up: 4inch valve installed at 12 o'clock position on 12" Oguta Assa Pipeline at Opuoma Picture was taken during Joint Investigation 15th July 2020.