



Overview: Part of spill impact on 8" Nkali ImoRiver 2 Pipeline at Odagwa. Picture was taken during Joint Investigation on 22nd July 2020.



Close-up: 1" Locally fabricated clamp installed alongside with 1" valve at 12 o'clock position on 8" Nkali - ImoRiver 2 Pipeline at Odagwa. Picture was taken during Joint Investigation on 22nd July 2020.