



Overview: Part of spill impact on 14" Okordia - Rumuekpe Pipeline at Ukpeliède. Picture was taken during Joint Investigation on 13th July 2020.



Close-up: Crude oil theft point installed at 12 o'clock position on 14" Okordia Rumuekpe Pipeline at Ukpeliède. Picture was taken during Joint Investigation on 13th July 2020.