




Overview: Part of spill impact on 14" Okordia - Rumuekpe Pipeline at Edeoha. Picture was taken during Joint Investigation of 1st Aug 2020.



Close-up: 15mm drilled hole installed at 12:15 o'clock position on 14" Okordia - Rumuekpe Pipeline at Edeoha. Picture was taken during Joint Investigation of 1st Aug 2020.