



9/1/2020 12:19:44 PM (+1.0 hrs) Lat=5.51316 Lon=5.19518 WGS-84

Overview: Part of spill impact on 24" Trans Escravos Pipeline at Ogidigben. Picture was taken during Joint Investigation on 1st September 2020.



9/1/2020 12:46:27 PM (+1.0 hrs) Lat=5.51309 Lon=5.19527 WGS-84

Close-up: Weld on 6" valve installed at 12 o'clock position on 24" Trans Escravos Pipeline at Ogidigben. Picture was taken during Joint Investigation on 1st September 2020.