




Overview: Part of spill impact on 28" Bomu - Bonny Pipeline at Owokiri . Picture was taken during Joint Investigation 2nd June 2020.



Close-up: 6" Full ball valve installed at 12 o'clock position on 28" Bomu - Bonny Pipeline at Owokiri . Picture was taken during Joint Investigation 2nd June 2020.