



Overview: Part of spill impact on 14" Okordia - Rumuekpe Pipeline at Ula-Ikata. Picture was taken during Joint Investigation of 7th June 2020.



Close-up: 1 of 2nos of smooth round-edge holes on 14" Okordia - Rumuekpe Pipeline at Ula-Ikata. Picture was taken during Joint Investigation of 7th June 2020



Close-up: 2 of 2nos of smooth round-edge holes on 14" Okordia - Rumuekpe Pipeline at Ula-Ikata.
Picture was taken during Joint Investigation of 7th June 2020