



Overview: Part of spill impact on New 20" Kolocreek - Rumuekpe Pipeline at Odau KP15.3. Picture was taken during Joint Investigation 9th June 2020.



Close-up: 4" ball valve installed at 12 o'clock position on New 20" Kolocreek - Rumuekpe Pipeline at Odau KP15.3 . Picture was taken during Joint Investigation 9th June 2020.