



Overview: Part of spill impact on 14" Okordia - Rumuekpe Pipeline at Edeoha. Picture was taken during Joint Investigation of 6th June 2020.



Close-up: Crude oil theft point installed at 12 o'clock position on 14" Okordia - Rumuekpe Pipeline at Edeoha. Picture was taken during Joint Investigation of 6th June 2020