



**Overview:** Part of spill impact on 36" Nkpoku - Ogale Pipeline at Rumuokwursi. Picture was taken during Joint Investigation 20th June 2020.



**Close-up:** 3 nos 3" bulb valves installed at 12 o'clock position on 36" Nkpoku - Ogale Pipeline at Rumuokwursi. Picture was taken during Joint Investigation 20th June 2020.