



		E 6.574040	Date 2020/06/19
		N 5.060931	Time 13:44:33 +01:00
		Altitude 10.600 M	Speed 0.03 KPH

Overview: Part of spill impact on 14" Okordia Rumuekpe Pipeline at Ula-Okobo. Picture was taken during Joint Investigation 19th June 2020.



Closeup 1: Crude Oil theft point installed at 12 o'clock position on 14" Okordia Rumuekpe Pipeline at Ula-Okobo. Picture was taken during Joint Investigation 19th June 2020.



Close-up 2: Crude Oil theft point installed at 12 o'clock position on 14" Okordia Rumuekpe Pipeline at Ula-Okobo. Picture was taken during Joint Investigation 19th June 2020.