


Overview: Part of spill impact on 12" ImoRiver 2 – Ogale Pipeline at Okohia. Picture was taken during Joint Investigation 2nd July 2020.



Close-up: plugged 2 nos 2inch Bulb valves installed at 12 o'clock position on 12" ImoRiver 2 – Ogale Pipeline at Okohia. Picture was taken during Joint Investigation 2nd July 2020.