




Overview: Part of spill impact on 4" Imo River 2\_ImoRiver 1 Bulkline at Odagwa. Picture was taken during Joint Investigation 30th June 2020.



Close-up: 7cm hacksaw cut from 8 o'clock position to a 6 o'clock position on 4" Imo River 2\_ImoRiver 1 Bulkline at Odagwa. Picture was taken during Joint Investigation 30th June 2020.