



Overview: Part of spill impact around Obele Flow station at Obele. Picture was taken during Joint Investigation of 10<sup>th</sup> March 2020.



Overview: Overflow from sump-pit on Obele Flow station at Obele. Picture was taken during Joint Investigation of 10<sup>th</sup> March 2020.



Close-up: Overflow from sewer-pit on Obele Flow station at Obele. Picture was taken during Joint Investigation of 10<sup>th</sup> March 2020.