




**Overview:** Part of spill impact on 20" Kolocreek Pipeline Right of Way at Okporowo. Picture was taken during Joint Investigation of 16<sup>th</sup> March 2020.



**Close-up:** 2" valve installed at 12 o'clock position showing water and oil on 20" Kolocreek Pipeline at Okporowo. Picture was taken during Joint Investigation of 16<sup>th</sup> March 2020.