



Overview: Part of spill impact on 28'' Nkpoku - Ebulu Pipeline at Rumuowha - Eneka. Picture was taken during Joint Investigation of 12th March 2020.



Close-up: 2'' valve crude oil theft points installed at 12 o'clock position on 28'' Nkpoku - Ebulu Pipeline at Rumuowha - Eneka. Picture was taken during Joint Investigation of 12th March 2020.