




Overview: Part of spill impact on 16" Egbema Assa Pipeline at Umudike. Picture was taken during Joint Investigation of 30th March 2020.



Close-up: 2nos 2" nipple (0.5m apart) installed at 12 o'clock position on 16" Egbema - Assa Pipeline at Umudike. Picture was taken during Joint Investigation of 30th March 2020.