



Overview: Part of spill impact on 12" Imo River2 – Ogale Pipeline at Umulolo. Picture was taken during Joint Investigation of 14th March 2020.



Close-up: 2 nos 1" valve installed 5m apart of crude oil at 12 o'clock position on 12" Imo River2 – Ogale Pipeline at Umulolo. Picture was taken during Joint Investigation of 14th March 2020.