



Overview: Part of spill impact on 6" North bank central processing facility condensate delivery line at Obotobo. Picture was taken during Joint Investigation of 6th May 2020.



Close-up: Irregular hole at 7 o'clock position on 6" North bank central processing facility condensate delivery line at Obotobo. Picture was taken during Joint Investigation of 6th May 2020.