



Overview: Part of spill impact on 28" Nkpoku Bomu Pipeline Right of way at B-Dere. Picture was taken during Joint Investigation of 2nd May 2020.



Close-up: 8" illegal valve connection at 12 o'clock position on 28" Nkpoku Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 2nd May 2020.