



Overview: Part of spill impact on 28" Nkpoku Bomu Pipeline at Elenwo. Picture was taken during Joint Investigation of 2nd May 2020.



Close-up: 6" valve crude theft point installed at 12 o'clock position on on 28" Nkpoku Bomu Pipeline at Elenwo. Picture was taken during Joint Investigation of 2nd May 2020.