



Overview: Part of spill impact on 16" Egbema Assa Pipeline at Etekwuru. Picture was taken during Joint Investigation of 7th May 2020.



Close-up: 3" Nipple installed at 12 o'clock position on 16" Egbema Assa Pipeline at Etekwuru. Picture was taken during Joint Investigation of 7th May 2020.