



**Overview:** Part of spill impact on 12" Imo River 2 Pipeline at Komkom . Picture was taken during Joint Investigation 30th May 2020.



**Close-up:** Crude oil theft point installed at 12 o'clock position on 12" Imo River 2 Pipeline at Komkom. Picture was taken during Joint Investigation 30th May 2020.