



Overview: Part of spill impact on 20'' Kolocreek-Rumuekpe Pipeline at Aminigboko . Picture was taken during Joint Investigation 30th May 2020.



Close-up: 3'' ball valve illegal connection installed at 12 o'clock position on 20'' Kolocreek - Rumuekpe Pipeline at Aminigboko . Picture was taken during Joint Investigation 30th May 2020.



Close-up: 3" ball valve illegal connection installed at 12 o'clock position on 20" Kolocreek - Rumuekpe Pipeline at Aminigboko . Picture was taken on 1st June 2020.