




Overview: Part of spill impact on 8" Agbada 2 - Nkpoku Pipeline at Rukpokwu. Picture was taken during Joint Investigation on 4th November 2020.



Close-up: Inward dent / Tear at 9 o'clock position on 8" Agbada 2 - Nkpoku Pipeline at Rukpokwu . Picture was taken during Joint Investigation on 5th November 2020.