



Overview: Part of spill impact on 18inch Assa Rumuekpe Pipeline at Akpabu. Picture was taken during Joint Investigation on 16th November 2020.



Close-up: 2inch valve illegal connection installed at 12 o'clock position on 18inch Assa Rumuekpe Pipeline at Akpabu. Picture was taken during Joint Investigation on 16th November 2020.