



Overview: Part of spill impact on 12inch Imo River 2 - Ogale Pipeline at Umulolo. Picture was taken during Joint Investigation on 24th November 2020



Close-up: 3inch valve connection welded on a flange at 12 o'clock position on 12inch Imo River 2 - Ogale Pipeline at Umulolo. Picture was taken during Joint Investigation on 24th November 2020