



Overview: Part of spill impact on 20inch Trans Escravos Pipeline at Ogidigben. Picture was taken during Joint Investigation on 11th November 2020.



Close-up: 4inch valve with 4inch elbow reduced to 3inch pipe installed at 12 o'clock position on 20inch Trans Escravos Pipeline at Ogidigben. Picture was taken during Joint Investigation on 11th November 2020.