




Overview: Part of spill impact on 16inch NunRiver – Kolocreek Pipeline at Otugwe. Picture was taken during Joint Investigation on 22nd November 2020.



Close-up: Point 1: 2nos hacksaw cut 75m apart at 12 o'clock on 16inch NunRiver – Kolocreek Pipeline at Otugwe. Picture was taken during Joint Investigation on 22nd November 2020.



Close-up: Point 2: 2nos hacksaw cut 75m apart at 12 o'clock on 16inch NunRiver – Kolocreek Pipeline at Otugwe. Picture was taken during Joint Investigation on 22nd November 2020.