



Overview: Part of spill impact on 12inch Imoriver 1 - Ogale Pipeline at Okohia.
 Picture was taken during Joint Investigation on 14th November 2020



Close-up: Locally fitted clamp with 1.5inch valve installed at 12 o'clock position on 12inch Imoriver 1 - Ogale Pipeline at Okohia.
 Picture was taken during Joint Investigation on 14th November 2020.