



Overview: Part of spill impact on 20'' Kolocreek –Rumuekpe Pipeline at Ihuowo. Picture was taken during Joint Investigation on 3rd October 2020.



Close-up: 3'' illegal valve with a concrete cast attached to a 3'' galvanized pipe at 12 o'clock position on 20'' Kolocreek –Rumuekpe Pipeline at Ihuowo. Picture was taken during Joint Investigation on 3rd October 2020.