



**Overview:** Part of spill impact on 14inch Okordia Rumuekpe Pipeline at Akala-Olu . Picture was taken during Joint Investigation on 14th October 2020.



**Close-up:** Leak point 1. A 2inch threaded ball valve of 98meters apart at 12 o'clock position A section of on 14inch Okordia Rumuekpe Pipeline at Akala-Olu . Picture was taken during Joint Investigation on 14th October 2020.



Close-up: Leak point 2 . A 3inch threaded ball valve of 98meters apart at 12 o'clock position A section of on 14inch Okordia Rumuekpe Pipeline at Akala-Olu . Picture was taken during Joint Investigation on 14th October 2020.