




Overview: Part of spill impact on 8'' Nkali ImoRiver 2 Pipeline at Nkali. Picture was taken during Joint Investigation on 6th October 2020.



Close-up: 1.5'' locally fabricated clamp with 1.5'' valve installed at 12 o'clock position on 8'' Nkali ImoRiver2 Pipeline at Nkali.
Picture was taken during Joint Investigation on 6th October 2020.