




01/11/2020 12:47:32 (+1.0 hrs) Lat=N04 58' 49.74" Lon=E007 10' 30.40" Alt=1ft MSL WGS-84

**Overview:** Part of spill impact on 12" Imo River2 - Ogale Pipeline at Igiriukwu isietitioha Owaza .  
Picture was taken during Joint Investigation on 1st November 2020.



01/11/2020 14:02:58 (+1.0 hrs) Lat=N04 58' 49.82" Lon=E007 10' 29.47" Alt=47ft MSL WGS-84

**Close-up:** 2nos crude oil theft points installed at 12 o'clock position on 12" Imo River2 - Ogale Pipeline at Igiriukwu isietitioha Owaza . Picture was taken during Joint Investigation on 1st November 2020.